

Hyperbaric Chamber Fires: Lessons Learnt

Dick Clarke, CHT

Hyperbaric Chamber Fires

Lessons Learnt

Primary Training in Hyperbaric Medicine
Columbia, South Carolina

Hyperbaric Chamber Fires

Lessons Learnt

Primary Training in Hyperbaric Medicine
Columbia, South Carolina

Factors Precipitating Chamber Fires

- Absence of design/manufacturing codes; code non-compliance
- Lack of a formal fire safety plan
- Inadequate fire safety plan
- Apparently adequate fire safety plan not adhered to
- Unanticipated factors

Absence of design/manufacturing codes: code non-compliance



Steel monoplace at 2.4 ATA
air compressed, mask O₂; inboard dump
no analyzer so unknown O₂ concentration

Flash fire
structural integrity maintained
hot gases melted door seal, cut through concrete floor, blew out building windows

Cause of ignition: non-intrinsically safe communication system



Intrinsically safe

- keeping level of electrical energy too low to cause ignition
thereby preventing sparks & keeping temperatures low
- device designs that exclude oxygen
plus, purging device with inert gas
- device strong enough to contain explosion
- moving device outside hazardous (chamber) area

No chamber design/construction codes & standards in Peru
some such countries adopt authoritative standards

Lack of adequate operational safety procedures

- no overboard O2 dump*
- unknown chamber O2 concentration*
- no pt. grounding*
- oil lubricated air compressor ? filtration*

Monoplace Chamber Fire
Lima, Peru, 2006
Incident Report
 Glenn J. Butler,
 President & CEO
 R.W. "Bill" Hamilton, Ph.D
 Hamilton Research
 Michael W. Allen
 Senior Vice President - Operations & Safety
 Life Support Technologies group

Absence of design/manufacturing codes: code non-compliance

Absence of design/manufacturing codes: code non-compliance

Lack of a formal fire safety plan

Lauderdale-by-the-Sea, Florida, May 2009

fire engulfed chamber & 2 occupants at 1.75 ATA O2
 ~ 4 yo CP pt., 62 yo grandmother
 ~ his tx started 7 months earlier!

operator (trainee) didn't know procedure for emergent decompression
 ~ tried several times to open door while pressurized

both occupants succumbed

Vickers "clam shell" manufactured in 1967

Burn pattern again suggested internal speaker as source

Legal proceedings:

Adult "reached to adjust cushion, static discharge from her clothing jumped to earphone jack"

Adult "banged on chamber for five minutes to attract attention"

"Nobody was monitoring them and when fire started victims were required to scream and bang on glass (sic) dome to get the attention of a bystander who in turn notified staff of the fire, which caused a delay in decompressing the chamber and freeing the victims before the flash fire occurred. When police deputies arrived, the victims were still in the chamber and on fire"

Numerous pages of safety violations

Most damning, set up fictitious inspection company
 "Certified Hyperbarics" for federal facility certification application

Medical Director & CHT "exhibited gross lack of competency, gross inattention, criminal indifference to pt. safety"

Both guilty of "aggravated manslaughter of a child & manslaughter by reckless disregard of human life & safety of persons exposed to dangerous effects"

Inadequate fire safety plan



Chamber operator opened 3-way valve to select BIBS O₂ source
 selected >2,000 psig (non-reduced) option
 reported hearing 'sizzling bacon' sound
 Fire immediately erupted from chamber control panel
 flame shot out 3 feet/1 meter, spraying molten stainless steel
 penetrated steel filing cabinet igniting contents
 chamber tech burned on face, arms, back, as she moved pt.
 fire extinguished only when O₂ supply secured
 Facility sprinkler system & fire alarm activated

News Briefs

Oxygen Fire at Shands Teaching Hospital in Gainesville, FL

*By David A. Schwartz, MPH, MSF
 Michael S. Wilson, PhD
 Steve J. Barber*

Hyperbaric Medicine Center Dedicated to Dr. Jefferson C. Davis

2nd International Meeting on High Pressure Biology

Desautels DA, et al. PRESSURE Nov/Dec 1990

Chamber Fire Analyzed

*By David A. Schwartz, MPH, MSF
 Michael S. Wilson, PhD
 Steve J. Barber*

Misc. Courses

Desautels DA, et al. PRESSURE Jan/Feb 1991

"Likely cause...high-velocity particle impacts"


ignited valve's Teflon seating & seal material
 several fittings significant for "sand blasting" appearance
 likely source of particles...HP O₂ cylinder valves & piping

Auto-ignition temperature of valve seating 400-700 F/200-370 C

particle friction heating in HP O₂ exceeds 1,600 F / 870 C

Lessons learned-safety standard failures

protect disconnected oxygen piping
 oxygen piping "cleaned for oxygen service"
 HP oxygen reduced at source
 quarter turn valves contraindicated
 filtration at source/prior to reducing regulator
 larger diameter piping reduces oxygen velocity/related heating



Apparently adequate fire safety plan not adhered to



Istanbul University Medical Center
 Multiphase chamber fire July 1998
 3 fatalities: 2 divers, 1 physician

Latter stages extended USN TT 6
 Chamber O₂ atmosphere not monitored nor routinely flushed
 one diver/pt. using mask with overboard exhaust, second using hood with inboard exhaust
 Two "lightsaber-like" oxygen flames seen emitting (via viewport)
 spontaneous ignition within regulators
 Chamber operator did not/could not activate water deluge
 Internal fire extinguisher not activated
 Flames only died out when oxygen system exhausted
 Relief valves lifted (10 ATA)

Inadequate system maintenance; particularly O2 delivery system cleanliness

Operational practices inconsistent with recognized standard of care

Physician entered chamber with cigarette lighter

"In all incidents I have encountered in my 30-year hyperbaric practice, the people who accidentally put a lighter or mobile phone inside are inside attendants and doctors, because patients are checked before each entrance"


Inadequate/non-existent emergency drills



Apparently adequate fire safety plan not adhered to



Steel oxygen-filled multiplace chamber
animal pt. fatality
chamber operator fatality



Patient treatment #5 underway
horse unsettled; kicking out
dislodged protective padding overlying steel hull
'massive spark' & flames per CCTV
urgent decompression initiated

Unanticipated factors



Youn B, et al. J Hyperbaric Med 1989;4(2)

Multiplace chamber at 2.0 ATA
2 inside attendants
4 patients; 3 adults, 1 4-wk-old
SOP microwave warming of blankets
some pediatric, all neonates

Cotton blanket warmed for 2.5 mins. high setting

Scorched (ironed shirt) smell upon removal

Examined by unfolding several times
nothing untoward/not unduly hot

Compressed in medical lock


Upon receipt into chamber IA noticed 2 brown spots
blanket immediately developed open flame

IA attempted to reinsert into lock

Chamber deluge activated...twice




Burned 100% cotton blanket




Carbon deposits below medical lock

Pts switched to air breathing
Poor visibility resulted in second deluge
All occupants uneventfully decompressed
Pts counseled & monitored; 3 inpts.
All eventually completed their HBO courses
Tested microwave warming 2.5-4.0 mins.
Scorching not obvious unless blanket fully opened



Scorched areas between creases at 2.5 mins.



Scorched areas between creases at 4.0 mins.

